Application Serial No. 10/573,769

Date: October 20, 2008

Response to Office Action dated September 19, 2008

Amendments to the Abstract:

Please replace the Abstract on page 21 of the application with the following Abstract:

Rotating drive shaft 11 is connected to a crankshaft and valve cam-13. Valve cam 13 lifts intake and exhaust valves[[,]] that are linked by a plurality of links-16-18. The amount of lift of intake and exhaust valves is adjusted by adjusting the position of a connector pin-22, which that passes through two links 16 and 18 and allows for their relative rotation. The adjustment of the connector pin 22 is configured so that it is performed from single adjustment direction 34 using prescribed adjustment tools-41 and 42.